

	ISS. LEVEL: 01	ISSUE DATE: 04 nd Oct 2016	SUPERSEDES: Form 190	PAGE: 1 of 2	AUTH. 
	DOC REF: AEU00654	TITLE: WORK INSTRUCTION – CLEAN MANUFACTURING AREA GOWNING PROCEDURE			

GOWNING UP PROCESS.



STEP 1.

**WEAR NEW HAIR CAP &
BEARD CAP IF NECESSARY**

STEP 2.


PUT ON OVERCOAT

STEP 3.

WEAR NEW OVERSHOES

	ISS. LEVEL: 01	ISSUE DATE: 04 nd Oct 2016	SUPERSEDES: Form 190	PAGE: 2 of 2	AUTH. 
	DOC REF: AEU00654	TITLE: WORK INSTRUCTION – CLEAN MANUFACTURING AREA GOWNING PROCEDURE			

REMOVING CMA CLOTHING.



STEP 1.

**REMOVE OVERSHOES AND THROW
AWAY**

STEP 2.

**REMOVE YOUR OVERCOAT,
RECYCLE IF DIRTY
OR RETURN TO HANGER**

STEP 3.

**REMOVE HAIR CAP
& THROW AWAY**