


ISS. LEVEL: 01	ISSUE DATE: 02 nd Dec 2014	SUPERSEDES: NONE	AUTH. 
DOC REF: AEU00494	TITLE: WORK INSTRUCTION – GOWNING PROCEDURE		

JEWELLERY MUST BE REMOVED BEFORE ENTERING CLEAN ROOM.
WEDDING RINGS TO BE COVERED WITH TAPE.
MAKE UP AND NAIL VARNISH MUST NOT BE WORN IN THE CLEAN ROOM



1 Hair net –
Ensure ears and all hair are covered



2 Beard snood- Persons with facial hair
(beards and or moustaches etc must cover them with a snood



3 Shoe covers –
Ensure covers do not touch floor in the 'grey' area. Once first shoe is covered straddle step and cover 2nd shoe



4 Overalls – Pull overalls over clothes.
Fasten all the way up. Loops on each sleeve must go over thumbs. Overalls must be replaced each week or sooner if damaged.



5 Sterilise hands –
Ensure sterilising solution is worked into hands. front and back and between fingers



6 Gloves– Pull gloves on over sleeve and sterilise using the sterilising solution by rubbing it on front and back of hands and between fingers

DE-GOWNING TO BE DONE IN REVERSE
GLOVES AND SHOE COVERS TO BE DISPOSED OF IN THE BIN FOUND IN THE 'GREY' AREA